## **Service Schematics**

## Introduction



## **Important:**

This document is intended for use by authorized service centers only.


RH-99/100

"Service Schematics" was created with focus on customer care. The purpose of this document is to provide further technical repair information for NOKIA mobile phones on Level 3/4 service activities. It contains additional information such as e.g. "Component finder".

Saving process time and improving the repair quality is the aim of this document. It is to be used additionaly to the service manual and other training or service information such as Service Bulletins.

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If the reader finds any errors, NOKIA should be notified in writing.


Please send E-Mail to: <u>TrainingAndVendor.Development@nokia.com</u>





## Copyright © NOKIA

Board version: 2bp\_30e

This material, including documentation and any related computer programs is protected by copyright, controlled by NOKIA. All rights are reserved. Copying, including reproducing, modifying, storing, adapting or translating any or all of this material requires the prior written consent of NOKIA. This material also contains confidential information, which may not be disclosed to others whitout the prior written consent of NOKIA.







								_						
В		C2918	M4	L2183	F8	R7105	L3			1 1	2	1 3	4	5
B2900	L4	C2919	L6	L2184	G7	R7110	L3			'	_		'	
B7402	К6	C2920	L3	L2400	N3	R7111	J1	_						
C		C2933	L3	L2402	03	R7112	K1		R	_				V2404
C2000	G3	C2937	M5	L7100	J5	R7113	L3						R2402 C2406	
C2001	H2	C2940	L6	L7102	I5	R7114	J4	j –					<u>№ [C2406]</u>	
C2002	G4	(2941	M6	L7103	K5	R7115	J4	İ	$\bigcirc$			~		
C2003	Q7	C2948	M5	L7105	J5	R7116	J4	İ				(2)		
C2004	R8	C2949	L6	L7106	K4	R7400	K5	i _		5	\( \)	$\mathcal{T}$		
C2005	Q7	C2950	K5	L7107	J5	R7401	16	İ				170		
C2006	Q7	C2951	L3	L7108	I5	R7402	I5	İ			(3)	7,		
C2007	S7	C7100	I3	L7109	J5	R7403	I5	_				<b>-</b> /		
C2008	R4	C7102	I1	L7110	I4	R7404	K6				,			
C2009	05	C7103	I1	L7112	J5	R7405	K6	ł	F					
C2010	06	C7103	L3	M	رر	R7407	M7	ł	_					
C2011	S5	C7104	I4	M2000	G6	V	1117	_				J2001		
(2013	R5	C7103	K2	112000 N	uu	V2000	<b>S7</b>			J2	2003—	++	-J2004	
(2013	N5	C7107	K2	N2150	05	V2000 V2001	P4	ł	ı			l i i	10000	
(2014		(7108	_				P4	-		J2	1000		-J2002	C2017
	N6		K4	N2400	03	V2002		ŀ	$\bigcirc$			C2000 R2000	N	
C2016	06	C7126	J1	N7100	J2	V2003	P3	ļ	G					
C2017	G5	C7127	J1	R		V2400	S6				$\rightarrow$	2005	12	
C2018	P6	C7128	I3	R2000	G3	V2401	04	ļ						
C2019	P6	C7130	I1	R2001	Q3	V2402	S4		Н		[2001] [2330]		ľ	
C2037	06	C7131	I3	R2002	R7	V2404	B5	ļ	' '		80			
(2151	04	C7132	K5	R2003	Q7	X		_		9				
C2152	S2	C7161	K5	R2004	R7	X2002	T5	[		(27.103/27.103/27.104/27.26/87.11/27.12/87.11)		C7100	[7110] C7105	C7403
C2154	N5	C7162	J5	R2005	Q7	X2005	G3		ı	02 0713				C7458
C2155	N5	C7400	K5	R2006	06	X2700	Q4	-		30 R710	N17.1	C7128		E [7112]
C2156	F8	C7403	I5	R2007	R4	Z		[	1	04[0712	N71	00	R7116	L7109 5 L7107 8
C2157	04	C7404	J5	R2009	05	Z2400	07	İ	$\cup$	6R711			ll I	7100
(2159	05	C7405	Ī5	R2010	S5	Z7100	J4	i –		107127				C7162 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\) C7132 \(\sigma\)
C2161	N5	C7406	K4	R2013	05	Z7101	<u>I4</u>	İ	1.7	R7112	C7107[C7108]			2317103 2
C2165	N5	C7407	К6	R2014	05	Z7102	K4	İ	K	$  \   \  ^{-}$	(2.32)			C2912C2950C7400
C2166	N6	C7408	K5	R2015	06			•				TP7101 +	+ 6 0 TP7 102	
C2167	E8	C7436	K6	R2018	P5			_				C2909 R7110 R7113 C2933		
C2168	E8	C7442	J8	R2020	R7							R7105 R7103 C2951		901
C2169	E8	C7444	I8	R2021	S5							C7104 R2908 C2910 C2920	101	TP7400
(2171	N5	C7445	K7	R2068	Q3			_				R2900		
C2171	05	C7446	K8	R2069	Q3				M			8 C2901	C2915 C2918 C	2937 <b>[</b> C2914] [C2913 <b>[</b> C
(2181	05	C7447	J8	R2070	Q3				IVI					
(2182	05	C7454	I6	R2150	N5			_						
			_						N I		_±		R	C2165 R2150 E
C2330	H2	C7455	J8	R2152	N5				$  \vee  $		J336	3   1.4		(2154) [2] (2154) [2]
C2400	04	C7456	17	R2153	N4			_						C2014   M2020   M202
C2401	N4	C7457	I6	R2154	05				$\sim$			N2400	2151 2160 2161 2161	
C2402	N8	C7458	I5	R2156	04				( )			[240] 24 [240] 22 [241]	V2401 C2157	2 E Z Z C200
C2403	N8	C7459	K5	R2158	05				0			2 (2410		harea     218
C2406	B4	C7463	M7	R2159	05			_				V2003	V200	¥
C2407	B4	C7464	I8	R2171	N5				$\triangleright$			J2849		R2018
C2408	B4	D		R2400	03				I			[20]		
C2409	03	D2901	L5	R2401	N4			_			J2063	R 2700		
C2410	03	D7400	L7	R2402	B4				$\bigcap$		1+_	R2001 R2069	V ? -	700
C2700	R3	D7402	J6	R2405	N6				V		(4/2/2	R2070	$\land \land \land$	700
C2701	R4	F		R2406	N6			_			~55 705	R2068		
C2901	М3	F2000	<b>S</b> 7	R2407	N6						J2060 3/2		[E] [E1017] 1c	1 E E
C2902	М3	Н		R2408	M6				R				R2007 (E	[201]
C2903	M6	H2400	N7	R2409	04								2402	/
C2909	L3	L		R2700	P3						(2152		7	
C2910	L3	L2000	<b>S</b> 7	R2900	M3				S		,		<i></i>	C201
(2911	K4	L2001	R5	R2901	L6				$\cup$		12011	12107		R201
(2912	K5	L2001	06	R2902	M6			_			J2011 J21	J2103 02		R20
(2913	M5	L2002	P6	R2908	L3				$\top$					
C2913		L2004 L2171	S2	R2908	M6				-					X2002
C2914 C2915	M5 M4	L2171 L2180	05	R7100				_			(			AZUU.
	-		_		J5				1 1					
C2916	K4	L2181	P5	R7103	L3				$\bigcup$			<del>                                     </del>		
C2917	M6	L2182	F8	R7104	J1			_					<u> </u>	
										1 1	2	3	4	15
										'	_		'	

[2011 | R2010 | R2021 J2 0 1 2

6

6

M2000

D7402

D7400

H2400

Z2400

C2004 R2004 R2005 R2005 R2005 R2002 C2006 R2002

0 C2007 . 2000

8

F2000

8

2169 (2168) (2167) (2183) (2156)

G